

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**CA382**  
**East**  
**1/2-1**  
**0.619 mi.**  
**3268 ft.**

**RESIDENTIAL**  
**2935 OCEAN PARKWAY**  
**BROOKLYN, NY**

**Site 1 of 3 in cluster CA**

**NY Spills** **S118459766**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**7 ft.**

**SPILLS:**

Name: RESIDENTIAL  
Address: 2935 OCEAN PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1508640 / 2015-12-01  
Facility ID: 1508640  
Facility Type: ER  
DER Facility ID: 471568  
Site ID: 517209  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 3101  
Spill Date: 2015-11-20  
Investigator: RMPIPER  
Referred To: Not reported  
Reported to Dept: 2015-11-20  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Private Dwelling  
  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2015-11-20  
Spill Record Last Update: 2015-12-01  
Spiller Name: Not reported  
Spiller Company: MANAGMENT COMP  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: ERICK SUTPHEN  
DEC Memo: "11/20/2015: Rashad Called Erick, he indicated that costumer ordered 1,000 gallons however the gauge was defective and that there was no whistle and during product transfer about 10-15 gallons came out of vent pipe. Erick said he confirmed that no product was in basement and it only came out of vent pipe. All boro is enroute to clean up discharged oil. According to PBS# 2-601442 there is a 5000 gallon #2 fuel oil tank aboveground on saddles. 2935 Ocean Parkway does not have an alternate address. There is another spill for this site that was closed on 10/30/1996 which was a tank overfill. 11/20/15- DEC Piper spoke with Chris Q. He is on site and soil under vent is saturated. It is apparent that there has been historical overfills in the past that have gone un reported and cleaned. They will continue to remove contamination. I directed All Boro to work over weekend to remove cont soil. He will contact me later with update and any issues . DEC Piper to follow up over weekend. 12/1/15- DEC Piper responded to site on 11/21/15, based on inspection it appears there was a historic # 6 oil spill out vent or from historic fill line. #2 oil spill has been cleaned and dug out. New spill has been opened to deal with historical #6 oil spill. This spill closed. "  
  
Remarks: "allboro is doing the clean up"

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

All Materials:

Site ID:	517209
Operable Unit ID:	1266297
Operable Unit:	01
Material ID:	2270158
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported